

Final Reclamation and Stormwater Inspection

March 17, 2025

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 319702

Well Name: DUMLER #1A

Inspection Document #: 718600400

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUMLER #1A
Location ID: 319702



Photo 1. Looking north down former access road. A small area of lower vegetation coverage is present the majority of access road appears to be progressing towards 80% coverage of reference areas.




Photo 2. Looking north across location. No oil and gas equipment remains. Vegetation is primarily weedy species such as Kochia, Russian thistle, Tansy and Blue mustard, Cheatgrass. Some desirable perennial vegetation is present on location. Noxious weeds were not observed at the time of inspection



Inspection Photos
Location Name: DUMLER #1A
Location ID: 319702




Photo 3. Looking north from well location. See photo 2 comments.



Photo 4. Looking west from wellbore. See photo 2 comments.



Inspection Photos
Location Name: DUMLER #1A
Location ID: 319702



Photo 5. Looking east from wellbore. See photo 2 comments.



Photo 6. Looking south from wellbore. See photo 2 comments.



Inspection Photos
Location Name: DUMLER #1A
Location ID: 319702



Photo 7. Reference vegetation to the north of well location.

