

# Final Reclamation and Stormwater Inspection

March 21, 2025

Operator: AXIS EXPLORATION LLC - 10646

Location ID: 320745

Well Name: COLUMBINE-STATE #1

Inspection Document #: 718600426

Arapahoe County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: COLUMBINE-STATE #1  
Location ID: 320745



**Photo 1.** Looking east down the tank battery access road. This road appears to be primary access to the eastern side of property.



**Photo 2.** Looking across the former tank battery. The loop at the end of the road remains. Oil and gas equipment has been removed.





Inspection Photos  
Location Name: COLUMBINE-STATE #1  
Location ID: 320745



**Photo 3.** picture taken at east side of location looking north. Loop at the end of the road appears to be unused and has not been reclaimed.



**Photo 4.** Looking south across former tank battery. The vegetation coverage is non uniform with large patches of bare soil. Vegetation coverage is less that the surrounding area.





Inspection Photos  
Location Name: COLUMBINE-STATE #1  
Location ID: 320745



**Photo 5.** Looking north across the tank battery. Non uniform vegetation coverage.



**Photo 6.** Reference vegetation to the south of the tank battery.





Inspection Photos  
Location Name: COLUMBINE-STATE #1  
Location ID: 320745



**Photo 7.** Well site is located approximately 1500 ft to the north of the tank battery across river. Picture taken looking west from main access road on the east side of river. Main access road appears to be used for property access.



**Photo 8.** Looking west from wellbore. No oil and gas equipment remains. Vegetation appears to be reflective of reference area.





Inspection Photos  
Location Name: COLUMBINE-STATE #1  
Location ID: 320745



**Photo 9.** Looking south from wellbore. See photo 8 comments.



**Photo 10.** Looking south from wellbore along former access road. Access road is reflective of reference vegetation.





Inspection Photos  
Location Name: COLUMBINE-STATE #1  
Location ID: 320745



**Photo 11.** Looking north from wellbore. See photo 8 comments.



**Photo 12.** Reference vegetation to the south of well location.

