

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768




Staining



Oily waste and staining

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Staining

Staining

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Debris



Debris

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Debris



Debris

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Open end tank valve



Debris

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768




Debris




??

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768




Debris. Staining.



Debris

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Oily waste and stained soil



Oily waste and stained soil

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**




Debris

Oily waste and stained soil

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Stained soil



Oily waste and staining

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Unused equipment



Tank berm washed out?

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Rebuilt tank berm



Evidence of tank berm failure?

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Debris



Incomplete tank berm

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Debris




Debris

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Leaking valve. No secondary plug.



Debris.

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Location from East corner



Location from South corner

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Location from West entrance



Location from North corner