

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Location Overview – Photo #07684



Location – Photo #07694

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Location – Photo #07699




Location – Photo #07701

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Location – Photo #07700



Location – Photo #07698



Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Illegible Battery Sign – Photo #07715



Illegible Wellhead Sign – Photo #07692

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Illegible Wellhead Sign – Photo #07693



Illegible Wellhead Sign – Photo #07694



Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Illegible Wellhead Sign – Photo #07695



Illegible Wellhead Sign – Photo #07696



Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Illegible Wellhead Sign – Photo #07697



Weeds – Photo #07714

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/21SWSE

Location ID: 335157

Date: 3/26/2025



Weeds – Photo #07713