

Inspection Photos

March 31st, 2025

Operator: Kinder Morgan - 46685

Location ID: 454942

Inspection Document #: 714002021

Dolores County, CO

Township: SESW 8 40N 17W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DC 22
Location ID: 454942

3/31/25
55° NE



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: DC 22
Location ID: 454942



Photo 2. View of cut a fill slopes that have not been recontoured per 1003 standards.

Inspection Photos
Location Name: DC 22
Location ID: 454942

