

## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7320 From entrance to location



Photo # 7321 Location

## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7322 Location



Photo # 7323 Location



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7324 Location



Photo # 7325 Location

## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7326 Location



Photo # 7327 Location



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7328 Location



Photo # 7329 Location

**Inspection/Audit Photos**  
**Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad**  
**Location #: 334939**



**Photo # 7330 Location**



**Photo # 7331 Location**



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Mar 25, 2025 at 1:44:00 PM  
CO

Photo # 7332 Location



Mar 25, 2025 at 1:44:41 PM  
CO

Photo # 7333 Location

## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7334 Location



Photo # 7335 Location



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7336 Location



Photo # 7337 Location



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7338 Location



Photo # 7339 Barbed wire laying on ground/wildlife hazard



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7340 Barbed wire laying on ground/wildlife hazard



Photo # 7341 Barbed wire laying on ground/wildlife hazard



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7342 Methanol tank lacks required information



Photo # 7343 Methanol tank lacks required information





## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



**Photo # 7344 Staining near tank battery**



**Photo # 7345 Staining near wellhead**



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



Photo # 7346 Staining near wellhead




Photo # 7347 Battery sign does not list all wells associated with tank battery/not in compliance with CECMC rules



## Inspection/Audit Photos

Location Name: QB Energy TWIN CREEK 1-15B (O1E) Pad

Location #: 334939



**Photo # 7348 PRV vent line on tank burner does not comply with CECMC pressure safety device rules or general safety rules.**



**Photo # 7349 Debris**