

Final Reclamation and Stormwater Inspection

March 28, 2025

Operator: AXIS EXPLORATION LLC - 10646

Location ID: 320094

Well Name: BULLARD #6

Inspection Document #: 718600453

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BULLARD #6
Location ID: 320094



Photo 1. Looking west from the former tank battery. There appears to be some erosion channels forming on the former access road near the tank battery. This area has less vegetation coverage than surrounding areas. The rest of the access road between the well location and tank battery appears to be reflective of surrounding vegetation.



Photo 2. Looking west from wellbore. Desirable vegetation appears to have established. The area near the fence line has been mowed.



Inspection Photos
Location Name: BULLARD #6
Location ID: 320094



Photo 3. Looking north from wellbore. List B noxious weed Scotch Thistle is present on location (red circle).



Photo 4. Looking east from wellbore. See photo 2 comments.



Inspection Photos
Location Name: BULLARD #6
Location ID: 320094



Photo 5. Looking south from wellbore. This area has some desirable plant establishment but it appears that vegetation coverage is lower than the surrounding area with some bare soil.



Photo 6. Looking east along the fence line south of the wellbore. It appears that the location extended past the fence.



Inspection Photos
Location Name: BULLARD #6
Location ID: 320094



Photo 7. List B noxious weed scotch thistle near the wellbore.



Photo 8. Reference vegetation to the west of well location.



Inspection Photos
Location Name: BULLARD #6
Location ID: 320094



Photo 9. Google earth aerial imagery taken 04/2024. It appears that the footprint of the well location and tank battery (red circle) extends over the fence line (approximate green line).