

## Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/12NWNW (HYRUP 12-11)

Location ID: 324042

Date: 04/3/2025



Apr 3, 2025 at 12:13:51 PM  
+39.368938,-108.064956 ±2.39m

Photo # 6874 Entrance to location



Apr 3, 2025 at 12:05:42 PM  
+39.369076,-108.063885 ±2.60m  
Parachute

Photo # 6865 Location/well has been plugged and abandoned

## Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/12NWNW (HYRUP 12-11)

Location ID: 324042

Date: 04/3/2025



Photo # 6866 Location/well has been plugged and abandoned



Photo # 6872 Location/well has been plugged and abandoned