

# Inspection Photos

April 3rd, 2025

Operator: MorningStar Operating - 10755

Location ID: 424696

Inspection Document #: 714002043

Archuleta County, CO

Township: NWNE 20 32N 5W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Navajo Lake 32-5 21-1, 2  
Location ID: 424696



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos  
Location Name: Navajo Lake 32-5 21-1, 2  
Location ID: 424696



**Photo 2.** Weedy debris have been removed from active pad.

Inspection Photos  
Location Name: Navajo Lake 32-5 21-1, 2  
Location ID: 424696



**Photo 3.** Wildlife netting at chemical tank secondary containment is no longer functioning.

Inspection Photos

Location Name: Navajo Lake 32-5 21-1, 2

Location ID: 424696



**Photo 4.** Russian olive has been removed from southern interim reclamation area. Note: Southern interim reclamation area remains with mostly bare soils, minimal vegetation was observed. Additional reclamation/seeding efforts are needed in this area.

