

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 4/3/2025



Location – Photo #07915



Location – Photo #07918

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 4/3/2025



Location – Photo #07912



Location – Photo #07911

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 4/3/2025



Unused Equipment – Photo #07916



Unused Equipment – Photo #07917

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 4/3/2025



Staining on Tank – Photo #07913



Staining on Tank – Photo #07914