

# Interim Reclamation and Stormwater Inspection

April 9, 2025

Operator: PONCHO PRODUCTION COMPANY - 71450

Location ID: 320629

Well Name: DTA-POEORIA #24

Inspection Document #: 718600478

Arapahoe County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DTA-POEORIA #24  
Location ID: 320629



**Photo 1.** Looking south across the location. Undesirable weeds such as Kochia are present throughout the location and not controlled.



**Photo 2.** Looking east towards tank battery. List B noxious weed Scotch Thistle is present throughout the location (red circle).





Inspection Photos  
Location Name: DTA-POEORIA #24  
Location ID: 320629



**Photo 3.** Inside containment around the tank battery. It does not appear that the fluid was removed.



**Photo 4.** Looking between the tanks to the northeast. See photo 3 comments.





Inspection Photos  
Location Name: DTA-POEORIA #24  
Location ID: 320629



**Photo 5.** Looking northwest behind the tank battery. Various debris and unused equipment is present.



**Photo 6.** Looking at the west side of southern tank. Fluid appeared wet. Approximately 2ft above ground level.





Inspection Photos  
Location Name: DTA-POEORIA #24  
Location ID: 320629



**Photo 7.** Looking east at pump shed on location. List C noxious weed Mullein is present on location (red circle). Debris is present around location.



**Photo 8.** Inside shed. Trash, chemicals and unused equipment.





Inspection Photos  
Location Name: DTA-POEORIA #24  
Location ID: 320629



**Photo 9.** Inside shed buckets with fluid/grease are present.



**Photo 10.** Pumpjack. Leaking fitting and stained soil beneath it (red circle).





Inspection Photos  
Location Name: DTA-POEORIA #24  
Location ID: 320629



**Photo 11.** Unused rod/ pipe stored on the east side of location.



**Photo 12.** Reference vegetation to the south of location.

