

Inspection Photos

April 8th, 2025

Operator: Abundance Energy - 10840

Location ID: 333602

Inspection Document #: 714002070

La Plata County, CO

Township: SESE 8 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Apr 8, 2025
288° W



Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



Photo 4. Gas line riser that remains in the northwest corner of the project area.

Apr 8, 2025
197° S



Photo 5. View of reference area composed predominantly of Sagebrush.