

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA FEDERAL #76

Location ID: 333226 API #: 05-113-06251

Inspection Date: 4/4/2025 Inspection Doc#: 693808310



Wellhead with fence during Bradenhead test



Separator and Meter housing

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA FEDERAL #76

Location ID: 333226 API #: 05-113-06251

Inspection Date: 4/4/2025 Inspection Doc#: 693808310



Tank battery
Liner exposed and torn on berms



Tank battery