

Inspection Photos

API: 017-07227

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 4/9/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing north toward the access road. The landowner road splits off to the east at the point and the remaining road dead ends at the former wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321873 | Date: 4/9/2025

Inspection Photos



Photo 2. Drone aerial photo facing north toward the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321873 | Date: 4/9/2025

Inspection Photos



Photo 3. Drone aerial photo facing west toward the former abandoned wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321873 | Date: 4/9/2025

Inspection Photos



Photo 4. Drone aerial photo facing north down toward the location. It appears they are impacted soil and an evident square outline a possible pit.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321873 | Date: 4/9/2025

Inspection Photos



Photo 5. Facing east toward the surrounding undisturbed rangeland.

