

# Final Reclamation and Stormwater Inspection

Date: 04/11/2025

Operator: TIMKA RESOURCES LTD - 88370

Location ID: 388515

Inspection Document #: 718700305

Logan County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources


Inspection Photos  
Location Name: Kirk A #1  
Location ID: 388515



**Photo 1.** Taken along the access road, facing east towards the former location. Road base was observed throughout the former road, which does not appear reflective of the adjacent reference areas.



Inspection Photos  
Location Name: Kirk A #1  
Location ID: 388515



**Photo 2.** The former well location does not meet vegetative standards with evidence of non-uniform vegetation cover resulting in areas of bare soils and debris observed throughout.



Inspection Photos  
Location Name: Kirk A #1  
Location ID: 388515



**Photo 3.** Continued from Photo 2, facing west. Debris observed throughout the former well location.