

# Inspection Photos

API: 017-07301

Operator: **GILBERT-STEWART OPERATING LLC**

Inspection Date: 4/10/2025

County: Cheyenne




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the wellsite. The pumpjack is disassembled and unused.



## Inspection Photos



**Photo 2.** Stained soils at the wellhead need to be cleaned up and properly disposed.





## Inspection Photos



**Photo 3.** The containment is full of oily fluid and needs to be properly disposed. Secondary containment must have wildlife protections to prevent entry.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources