

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SEW

Location ID: 335264

Date: 4/9/2025



Location Overview – Photo #08063



Location – Photo #08064

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SEW

Location ID: 335264

Date: 4/9/2025



Location – Photo #08065



Location – Photo #08066

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SEW

Location ID: 335264

Date: 4/9/2025



**PRV Terminates in Unsafe Manner – Photo #08068**

**PRV Terminates in Unsafe Manner – Photo #08069**

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SEW

Location ID: 335264

Date: 4/9/2025



Stored Supplies – Photo #08072