

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 945 From entrance to location



Photo # 946 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 947 Location



Photo # 948 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 949 Location



Photo # 950 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 951 Location




Photo # 952 Labeling on separator unit shows previous operator name & phone #



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 953 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 954 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 955 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 956 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 957 Open ended load line



Photo # 958 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 959 Hole in liner/liner needs maintenance



Photo # 960 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 961 Hole in liner/liner needs maintenance



Photo # 962 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 963 Tank label contains inaccurate information




Photo # 964 Tank label contains inaccurate information



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms J Pad

Location ID: 416703



Photo # 965 Tank label contains inaccurate information

