

Inspection Photos

04/16/2025

Operator: CAERUS PICEANCE LLC #10456

Location ID: 413221

Inspection Doc: 718100420

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 1: Photos taken from the north end of the working pad surface. Photos examples showing stockpiled material is “flowing over” beyond the liner/containment in place. Various trash/debris/rubbish also observed mixed with the stockpiled material.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 2: Continued from photo 1. Photos examples showing holes and tears exist throughout the liner placed beneath of the stockpiled materials.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 3: Continued from photo 1. Photos examples showing stockpiled material is “flowing over” beyond the liner/containment in place, and that holes and tears exist throughout the liner



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 4: Continue from photo 1. Photo example showing vehicle/equipment travel over the stockpiled materials and containment measures.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 5: Photos show an additional stockpile of excavated material. No liner is evident at stockpile. Various trash/debris/rubbish also observed mixed with the stockpiled material.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 6: Photos examples showing signage missing from wells.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 7: Photos example showing tracking/degradation observed on the working pad surface. Various trash/debris/rubbish also observed within the ruts

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 5: Unused equipment/debris observed on the south end of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413221



Photo 9: Photos taken from the west end of the Location. Photos examples showing weeds (Common mullein) established on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources