

**Inspection Photos**  
**Location Name: Musick McClintock 1**  
**Location ID: 332862**



**Photo 1 well head and equipment**




**Photo 2 well head and equipment**

**Inspection Photos**  
**Location Name: Musick McClintock 1**  
**Location ID: 332862**



**Photo 3 stained soil crude tank drain**



**Photo 4 production equipment**