

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2364 From Entrance to location




Photo # 2365 Location

Inspection Photos
Location Name: QB Energy STI 29-7C (A29NE) Pad
Location #: 335178



Photo # 2366 Location



Photo # 2367 Location

Inspection Photos
Location Name: QB Energy STI 29-7C (A29NE) Pad
Location #: 335178



Photo # 2368 Location



Photo # 2369 Location

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2370 Hole in liner/liner needs maintenance



Photo # 2371 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2372 Hole in liner/liner needs maintenance



Photo # 2373 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2374 Hole in liner/liner needs maintenance



Photo # 2375 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2376 Hole in liner/liner needs maintenance



Photo # 2377 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: QB Energy STI 29-7C (A29NE) Pad
Location #: 335178



Photo # 2378 Holes in liner/liner needs maintenance




Photo # 2379 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2380 Hole in liner/liner needs maintenance



Photo # 2381 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2382 Hole in liner/liner needs maintenance



Photo # 2383 Hole in liner/liner needs maintenance & liner showing signs of deterioration

Inspection Photos
Location Name: QB Energy STI 29-7C (A29NE) Pad
Location #: 335178



Photo # 2384 Holes in liner/liner needs maintenance & liner showing signs of deterioration



Photo # 2385 Holes in liner/liner needs maintenance & liner showing signs of deterioration

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2386 Hole in liner/liner needs maintenance & liner showing signs of deterioration



Photo # 2387 Hole in liner/liner needs maintenance & liner showing signs of deterioration

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2388 Hole in liner/liner needs maintenance & liner showing signs of deterioration



Photo # 2389 Hole in liner/liner needs maintenance & liner showing signs of deterioration

Inspection Photos

Location Name: QB Energy STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 2390 Hole in liner/liner needs maintenance & liner showing signs of deterioration



Photo # 2391 Flowline heating insulation open ended /wildlife hazard/available for entry by wildlife