

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad
Location ID: 335447



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Section/Township/Range: 16 6S91W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad
Location ID: 335447



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad
Location ID: 335447



Photo # 1642 Lack of stabilization on cut slope/BMP's need maintenance



Photo # 1643 Lack of stabilization on cut slope/BMP's need maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad
Location ID: 335447



Photo # 1644 Lack of stabilization on cut slope/BMP's need maintenance



Photo # 1645 Lack of stabilization on cut slope/BMP's need maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 23-16 Pad
Location ID: 335447



Photo # 1646 Lack of stabilization on cut slope/BMP's need maintenance



Photo # 1647 Lack of stabilization on cut slope/BMP's need maintenance