

Final Reclamation Inspection

April 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 331629

Inspection Document #: 718800165

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CERVI #24-35
Location ID: 331629



Photo 1. Photo taken from the well location, facing North. It appears Operator has performed final reclamation activities with evidence of seeding, however vegetation does not meet Rule 1004 final reclamation standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: CERVI #24-35
Location ID: 331629



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CERVI #24-35
Location ID: 331629



Photo 5. Photo taken of the tank battery location, facing Southwest. Photo illustrates that there is evidence of seeding activities, but site does not meet Rule 1004 standards as sufficient native perennial vegetation has not established at the site.



Photo 6. Photo taken of the tank battery location, facing Northwest. See comments under Photo 5.

Inspection Photos
Location Name: CERVI #24-35
Location ID: 331629



Photo 7. Photo taken of the access road, facing Southwest towards the location. Photo illustrates that the site does not meet Rule 1004 standards as there is weedy growth and vegetation does not reflect reference area conditions.



Photo 8. Photo taken of the access road, facing Northeast, away from the location. See comments under Photo 7.

Inspection Photos
Location Name: CERVI #24-35
Location ID: 331629



Photo 9. Photo taken of the vegetation along the access road. See comments under Photo 7.



Photo 10. Photo taken of the reference area, north of the location, facing East.