

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35NWSW

Location ID: 334629

Date: 4/21/2025



Location Overview – Photo #08271



Location Overview – Photo #08272

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35NWSW

Location ID: 334629

Date: 4/21/2025



Location – Photo #08273



Location – Photo #08284



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35NWSW

Location ID: 334629

Date: 4/21/2025



Location – Photo #08287



Location – Photo #08293



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35NWSW

Location ID: 334629

Date: 4/21/2025



Location – Photo #08294



Illegible Wellhead Sign – Photo #08274



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35NWSW

Location ID: 334629

Date: 4/21/2025



Illegible Wellhead Sign – Photo #08276



Illegible Wellhead Sign – Photo #08278

## Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35NWSW

Location ID: 334629

Date: 4/21/2025



Faded Wellhead Sign – Photo #08280



Peeling Tank Label – Photo #08291



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35NWSW

Location ID: 334629

Date: 4/21/2025



Unused Equipment – Photo #08282



Unused Equipment – Photo #08283

