

Interim Reclamation and Stormwater Inspection

April 15, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 464916

Location Name: Dottie Doris/11,12-34

Inspection Document #: 718600514

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dottie Doris/11,12-34
Location ID: 464916



Photo 1. North side of the tank battery. Sign reads DOTTIE 11-33.



Photo 2. Looking at the east side of the tank battery. Weeds have been mowed on location and in secondary containment. Trash has been removed.



Inspection Photos
Location Name: Dottie Doris/11,12-34
Location ID: 464916



Photo 3. Looking at the east side of the northern tank. Animal holes are present underneath the tank.



Photo 4. Photo taken on the east side of location. PVC pipes behind the tanks do not have wildlife exclusion devices installed.

