

Inspection Photos

04/14/2025

Operator: LARAMIE ENERGY LLC #10433

Location ID: 312427

Inspection Doc: 718100476

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312427



Photo 1: Photos taken from the west end of the Location, facing northeast and southeast. Photos provide an overview of the Location; vegetation on the Location is not progressing towards ECMC 1004 uniform, desirable perennial vegetative requirements; vegetation established is predominantly Undesirable Plant Species including Kochia, Russian Thistle and Redstem Filaree; perennial establishment throughout the Location is sparse.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312427



Photo 2: Continued from photo 1. Photos examples showing weed establishment (Russian thistle). Vegetation on the Location is not progressing towards ECMC 1004 uniform, desirable perennial vegetative requirements; vegetation established is predominantly Undesirable Plant Species including Kochia, Russian Thistle and Redstem Filaree; perennial establishment throughout the Location is sparse.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312427



Photo 3: Continued from photo 2. Green vegetation beneath the weed debris is Kochia establishing on the Location. Perennial establishment throughout the Location is sparse.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312427



Photo 4: Photo example showing sparse perennial vegetation (green vegetation in photo).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312427



Photo 5: Photos taken from the south end of the Location. Operator has submitted a variance request to waive 1004 reclamation requirements of approximately “98 feet of access road”. Vegetation established on the access road is predominantly weeds, including cheatgrass and redstem filaree.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources