

Inspection Photos
Location Name: Pagel 43-34-4N47W
API Number: 125-09242



1. Lease sign at well location.



2. View of wellhead.


Inspection Photos

Location Name: Pagel 43-34-4N47W

API Number: 125-09242



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Pagel 43-34-4N47W
API Number: 125-09242



5. Broken door handle on meter shed door. Door is jammed shut.



6. Gathering location overview.