

# Inspection Photos

04/16/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 414880

**Inspection Doc:** 718100498

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 1:** Photos taken from the Location entrance. Photos show that the Location's entrance was unlocked and open at time of inspection, and that vehicle ruts throughout the site was observed and has resulted in additional degradation to the site, and the reclamation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 2:** Continued from photo 1. Photos show vehicle ruts observed throughout the site, resulting in degradation to the Location and the reclamation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 3:** Photos taken from the northern areas of the Location. Vegetation is not progressing towards ECMC 1004 uniform, desirable perennial vegetative cover requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 4:** Continued from photo 3. Photos examples showing erosion degradation, and sediment transport/deposition observed on the north end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 5:** Photos taken from the eastern areas of the Location. Vegetation within these areas are progressing towards ECMC 1004 uniform, desirable perennial vegetative cover requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 6:** Photos taken from the southern areas of the Location. Vegetation within these areas are progressing towards ECMC 1004 uniform, desirable perennial vegetative cover requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 7:** Photos examples showing weed rosettes observed on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414880



**Photo 8:** Fence along the perimeter of the Location is in disrepair.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources