


**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**



**Photo # 6114 From entrance to location**



**Photo # 6115 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**



**Photo # 6116 Location**



**Photo # 6117 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**



**Photo # 6118 Location**



**Photo # 6119 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**



**Photo # 6120 Location**



**Photo # 6121 Flowline heating insulation open ended  
/wildlife hazard/available for entry by wildlife**

**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**




**Photo # 6122 BOULTON 33-6 BH line tied into flowline**




**Photo # 6123 BOULTON 33-6 BH line tied into flowline & also tied into separator at the A valve bypass**

**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**



**Photo # 6124 BOULTON 33-6 BH line tied into flowline & also tied into separator at the A valve bypass**



**Photo # 6125 BOULTON 33-6 BH line tied into flowline & also tied into separator at the A valve bypass**

**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**




**Photo # 6126 BOULTON 33-6 BH line tied into separator at the A valve bypass**



**Photo # 6127 BOULTON 33-6 BH line tied into separator at the A valve bypass**

**Inspection/Audit Photos**  
**Location Name: QB Energy BOULTON 33-6 (F33) Pad**  
**Location ID: 334859**



**Photo # 6128 BOULTON 33-6 BH line tied into separator at the A valve bypass**



**Photo # 6128 BOULTON 33-6 BH line tied into separator at the A valve bypass**

## Inspection/Audit Photos

Location Name: QB Energy BOULTON 33-6 (F33) Pad

Location ID: 334859



**Photo # 6130 BOULTON 33-6 BH line tied into separator at the A valve bypass**

