

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666



Photo # 6445 From entrance to location



Photo # 6446 Location

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666



Photo # 6447 Location



Photo # 6448 Location

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666



Photo # 6449 Location



Photo # 6450 Location

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666



Photo # 6451 Location



Photo # 6452 Location

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666



Photo # 6453 Location



Photo # 6454 Location

Inspection/Audit Photos

Location Name: QB Energy JUNIPER 1-13A (M1E) Pad

Location #: 334666



**Photo # 6455 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 6456 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**

Inspection/Audit Photos

Location Name: QB Energy JUNIPER 1-13A (M1E) Pad

Location #: 334666



Photo # 6457 Flowline heating insulation damaged/wildlife hazard/available for entry by wildlife



Photo # 6458 Unmarked deadman

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666



Photo # 6459 Same unmarked deadman



Photo # 6460 Same unmarked deadman from a different angle

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666



Photo # 6461 JUNIPER 2-16 (M1E) well




Photo # 6462 JUNIPER 2-16 (M1E) well

Inspection/Audit Photos
Location Name: QB Energy JUNIPER 1-13A (M1E) Pad
Location #: 334666




Photo # 6463 JUNIPER 2-16 (M1E) well



Photo # 6464 JUNIPER 2-16 (M1E) well

Inspection/Audit Photos

Location Name: QB Energy JUNIPER 1-13A (M1E) Pad

Location #: 334666



Photo # 6465 Partially buried valve on the JUNIPER 2-16 (M1E) well (possibly SC BH valve or IC BH valve)



Photo # 6466 Partially buried valve on the JUNIPER 2-16 (M1E) well (possibly SC BH valve or IC BH valve)