

Final Reclamation and Stormwater Inspection

Date: 04/23/2025

Operator: PDC ENERGY INC - 69175

Location ID: 327364

Inspection Document #: 718700355

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Annie 3-9
Location ID: 327364



Photo 1. Facing north. The well location (Location ID 327364 with API 123-14566) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and production facilities have been superseded by a land use change to a sand and gravel mining operation (Permit #M2010049). Reclamation jurisdiction will now transfer to the Division of Reclamation, Mining and Safety.

Inspection Photos
Location Name: Annie 3-9
Location ID: 327364



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Annie 3-9
Location ID: 327364



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: Annie 3-9
Location ID: 327364



Photo 4. Facing west; see comments in Photo 1.