

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404188096

Date Received:

05/02/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Byars, Amy

abyars@mspartners.com

Blaylock, Connie

cblaylock@mspartners.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002043

Inspection Date: 04/03/2025

FIR Submit Date: 04/04/2025

FIR Status: _____

Inspected Operator Information:

Company Name: MORNINGSTAR OPERATING LLC

Company Number: 10755

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 424696

Location Name: NAVAJO LAKE 32-5 Number: 21-2 County: _____

Qtrqtr: NWNE Sec: 20 Twp: 32N Range: 5W Meridian: N

Latitude: 37.009970 Longitude: -107.414790

FACILITY - API Number: 05-007- -00 Facility ID: 424696

Facility Name: NAVAJO LAKE 32-5 Number: 21-2

Qtrqtr: NWNE Sec: 20 Twp: 32N Range: 5W Meridian: N

Latitude: 37.009970 Longitude: -107.414790

CORRECTIVE ACTIONS:

1 CA# 203883

Corrective Action: comply with rule 608 Install or repair wildlife protection equipment.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/29/2025

Operator
Comment:

The chemical tank that the netting was protecting was removed from the location.

ECMC Decision: _____

Reseeding has been completed.

BMP maintenance completed.

3 corrective actions have been completed as of 5/1/25.

Date: 5/2/2025 10:09:07 AM

Page 2 of 2