

WELL NAME: AC 1-8, API #: 071-07900, INSP. # 716300916



PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: 25 BBL PRODUCED WATER TANK, COMPRESSOR AND METER HOUSE.





PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 5-10-2025.





PHOTO 6: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 5-10-2025.



PHOTO 7: OILY WASTE IN COMPRESSOR SKID HAS NO NETTING FOR WILDLIFE PROTECTION. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. . CA DATE 4-30-2025.





PHOTO 8: THE ENTIRE COMPRESSOR SKID IS SATURATED WITH OILY WASTE FROM SEVERE OIL LEAKS. REPAIR AND CLEAN UP EQUIPMENT.

