

Inspection Photos

Loc: 488239

Operator: BNL (ENTERPRISE) INC

Inspection Date: 5/1/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. The road will need to be maintained per 1002.f. rules.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:488239 | Date: 5/1/2025

Inspection Photos



Photo 2. Facing north along the access road. The soils are very loose and susceptible to erosion.



Inspection Photos



Photo 3. Northeast side of the location facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:488239 | Date: 5/1/2025

Inspection Photos



Photo 4. East side of the location facing south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:488239 | Date: 5/1/2025

Inspection Photos



Photo 5. West side of the location facing northeast toward the topsoil pile.

