

Inspection Photos

Loc: 483009

Operator: BNL (ENTERPRISE) INC

Inspection Date: 5/1/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the pre-existing access road. The road will need to be maintained per 1002.f. rules.



Inspection Photos



Photo 2. Facing north along the pre-existing access road near the location site. An access road will need to be built off of this road to the new location. Topsoil along the access road will need to be salvaged.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483009 | Date: 5/1/2025

Inspection Photos



Photo 3. Facing east toward the location which construction has not yet commenced.

