

# Final Reclamation Inspection

April 17, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 331947

Inspection Document #: 718800190

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: WARDELL #18-29  
Location ID: 331947



**Photo 1.** Photo taken from the well location, facing North. Operator has performed final reclamation activities with evidence of drill row seeding, however vegetation does not meet Rule 1004 final reclamation standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: WARDELL #18-29  
Location ID: 331947



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: WARDELL #18-29  
Location ID: 331947



**Photo 5.** Photo taken from the perimeter of the well location, facing South. Photo illustrates barbed wire fencing that remains in place surrounding the well location. Russian thistle (*Salsola tragus*) was observed collected in the fence.



**Photo 6.** Photo taken from the access road, facing west, away from the well location. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows, but vegetation establishment does not meet final reclamation standards.



Inspection Photos  
Location Name: WARDELL #18-29  
Location ID: 331947



**Photo 7.** Photo taken from the reference area, north of the well location, facing East. Photo illustrates that the reference location is disturbed rangeland with bare ground patches and shrub and perennial grass vegetation.