

Final Reclamation Inspection

April 23, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 417179

Inspection Document #: 718800230

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: COTTONWOOD TANK
BATTERY #12-33
Location ID: 417179



Photo 1. Photo taken from the tank battery location, facing Southwest. Photo illustrates that final reclamation has taken place, with evidence of drill rows from reseeded.



Photo 2. Photo taken from the tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: COTTONWOOD TANK BATTERY
#12-33
Location ID: 417179



Photo 3. Photo taken from the access road, facing northeast, towards the location. Photo illustrates that access road has not been reclaimed.



Photo 4. Photo taken from the access road, facing Southwest, away from the location. See comments under Photo 3.

Inspection Photos
Location Name: COTTONWOOD TANK BATTERY
#12-33
Location ID: 417179



Photo 5. Photo taken of the reference area, south of the location, facing East. Photo illustrates area is dominated by perennial grass vegetation.