


Approximate spill location (former produced water vault).









WGS84  
±9ft

40.29275, -105.02759

Λ<sup>m</sup>  
±3m

1498



°T  
±11

W264

ECMC  
Environmental  
Field Inspection



Schaal 64N68W 20SESW  
© 06-May-25 11:18:58 AM  
ECMC Environmental Inspection

Depressions visible at gas line location.





Approximate location of former separators and emission control devices.