

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 386 From entrance to location




Photo # 387 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 388 Location



Photo # 389 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 390 Location



Photo # 391 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 392 Unmarked deadman



Photo # 393 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 394 Emergency contact # on wellhead sign incorrect



Photo # 395 Emergency contact # on wellhead sign incorrect

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 396 Barbed wire laying on the ground/wildlife hazard



Photo # 397 Barbed wire laying on the ground/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 398 Barbed wire laying on the ground/wildlife hazard



Photo # 399 Barbed wire laying on the ground/wildlife hazard