

Inspection Photos

API: 017-07388

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 5/13/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road. Operator has indicated that a variance will be sought for the road to remain.



Inspection Photos



Photo 2. Facing south toward the location. The access road contuse thru the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321902 | Date: 5/13/2025

Inspection Photos



Photo 3. Facing south at the location. The soils have been decompacted and seeded. There was manure and straw mulch applied to disturbed areas.

