

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA FEDERAL #64

Location ID: 334216

API #: 05-113-06225

Inspection Date: 5/12/2025 Inspection Doc#: 693808638



Wellhead with fence



Separator and Meter housing



Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA FEDERAL #64

Location ID: 334216

API #: 05-113-06225

Inspection Date: 5/12/2025 Inspection Doc#: 693808638



Tank battery



**Tank battery
Berms inadequate**



Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA FEDERAL #64

Location ID: 334216

API #: 05-113-06225

Inspection Date: 5/12/2025 Inspection Doc#: 693808638



Fresh water tank



Location overview

