

WELL NAME: BURRO CANYON 34-28, API #: 071-06112, INSP. # 716300978



PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: PRODUCED WATER TANK BATTERY. NFPA, CAPACITY AND CONTENTS NOT LABELED ON TANK. Install sign to comply with Rule 605.h. CA DATE 5/19/2025.





PHOTO 5: BIRD PROTECTORES MISSING OR NOT INSTALLED ON TWO PIPES IN TOP OF TANK. **INSTALL BIRD PROTECTORS. CA**
DATE 5/19/2025.





PHOTO 6: UNUSED EQUIPMENT (SHED DOES NOT APPEAR TO BE IN USE OR USEFUL TO THE OPERATION OF THIS FACILITY, SHED IS DETERIORATING AND TRASH AND DEBREE FROM SHED IS ON AND AROUND LOCATION). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 6/14/2025.





**PHOTO 7: UNUSED EQUIPEMENT (UNUSED RISERS NOT MARKED OR LABELED INSIDE UNUSED SHED). MARK OR REMOVE
UNUSED AND OR UNNESSESARY RISERS PER RULE 606. CA DATE 6/14/2025.**





PHOTO 8: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED. INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606. CA DATE 5/19/2025.





PHOTO 9: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED. INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606. CA DATE 5/19/2025.



PHOTO 9: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED. INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606. CA DATE 5/19/2025.



PHOTO 10: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED. INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606. CA DATE 5/19/2025.



PHOTO 11: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED. **INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606. CA DATE 5/19/2025.**



PHOTO 12: TRASH AND OR DEBREE FROM DETERIORATING SHED ON AND AROUND LOCATION MOSTELY TO THE SOUTH AND SOUTHEAST OF SHED. INSPECT AND REMOVE ALL TRASH AND DEBREE FROM LOCATION AND SURROUNDING AREA PER RULE 606. CA DATE 5/19/2025.