

Interim Reclamation and Stormwater Inspection

May 13, 2025

Operator: BISON IV OPERATING LLC- #10670

Location ID: 462908

Inspection Document #: 697505906

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Little Lady 21/South Well Pad

Location ID: 462908



Photo 1. Photo taken from the southeastern location, facing North. Photo illustrates interim reclamation areas that were dominated by weedy, annual vegetation consisting of Russian thistle have been mowed. Desirable germination was observed throughout most areas but is lacking some along the eastern area.



Photo 2. Close up photo illustrating the Russian thistle growth.

Note- Russian thistle growth was observed throughout the interim area and in need of weed management.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 697505906

Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462908



Photo 3. Photo taken from the northern location, facing North.
See comments under Photo 1.



Photo 4. Photo taken from the western location, facing Southwest.
See comments under Photo 1.

Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462908



Photo 5. Photo taken from the topsoil stockpile, facing West. Photo illustrates desirable vegetation is in process with the composition of weedy, annual vegetation.