

Interim Reclamation and Stormwater Inspection

May 13, 2025

Operator: BISON IV OPERATING LLC- #10670

Location ID: 454351

Inspection Document #: 697505909

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SALT RANCH FEE 10 East
Location ID: 454351



Photo 1. Photo taken from the western interim area, facing North. Photo illustrates interim reclamation areas are a mix of annual wheat grass (not desirable), western wheatgrass (desirable), and weedy, annual vegetation which includes cheatgrass. Desirable germination was mostly observed along the western area, while the north and east were predominantly weedy, annual vegetation.



Photo 2. Photo taken along the northwestern interim area, facing West. Photo illustrates where a previous access road was removed with sparse desirable germination.



Inspection Photos
Location Name: SALT RANCH FEE 10 East
Location ID: 454351



Photo 3. Photo taken from the northwestern interim area, facing East. See comments under Photo 1.



Photo 4. Photo taken from the northeastern interim area, facing East. Photo illustrates weedy, annual vegetation.



Inspection Photos
Location Name: SALT RANCH FEE 10 East
Location ID: 454351



Photo 5. Photo taken from the northeastern interim area, facing South. See comments under Photo 4.



Photo 6. Photo taken from the topsoil stockpile, facing South. Photo illustrates weedy, annual vegetation consisting of annual wheat grass, tumbleweeds and cheatgrass.

