

## Inspection Photos

Location Name: 70 Ranch USX BB/35-01P

Location #: 415988



**Photo #1**

**70 Ranch USX BB 35-01P (123-31283) Wellsite**

**Plugging & Abandoned | PA**

**Plugging Ops; Cementing: cut-csg; base plug**



**Photo #2**

**70 Ranch USX BB 35-01P Wellsite**

**Plugging & Abandoned | PA**

**Plugging Ops; Cementing: cut-csg; base plug**

*Site safety signage*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



# Inspection Photos

Location Name: 70 Ranch USX BB/35-01P  
Location #: 415988



Colorado Energy & Carbon Management Commission  
Weld County  
+40.359264, -104.398705  
45° NE  
2025-05-09 13:54


Photo #3

70 Ranch USX BB 35-01P Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cut-csg; base plug

Wellsite(s) entrance



Colorado Energy & Carbon Management Commission  
Weld County  
+40.360982, -104.396629  
159° S  
2025-05-09 13:48

Photo #4

70 Ranch USX BB 35-01P Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cut-csg; base plug

JSA: 2025-05-09



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources