

# Inspection Photos

API: 017-07700

Operator: **VECTA OIL & GAS LTD**

Inspection Date: 5/19/2025

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east at the beginning of the access road. The cattleguard remains and the fence has not been repositioned back in line with original fence line..



## Inspection Photos



**Photo 2.** Drone aerial photo facing south overlooking the location.



## Inspection Photos



**Photo 3.** Drone aerial photo facing north toward the location.



## Inspection Photos



**Photo 4.** Facing west at the surrounding area which has interspersed bare areas along with areas of native vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources