

# Inspection Photos

API: 017-07705

Operator: **VECTA OIL & GAS LTD**

Inspection Date: 5/19/2025

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** The area where the cattle existed is now fenced off. This area has accumulated sand and has filled in the cattle guard. Arrow points to the two cattle guard posts. The cattle guard will need to be removed and area reclaimed.

Lat/Long: 38.86674/-102.66708



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-07705 | Date: 5/19/2025



## Inspection Photos



**Photo 2.** Center of the location facing north. Perennial vegetation has reestablished to reference area levels.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Center of the location facing west. Perennial vegetation has reestablished to reference area levels.





## Inspection Photos



**Photo 4.** Center of the location facing south. Perennial vegetation has reestablished to reference area levels.





## Inspection Photos



**Photo 5.** Center of the location facing east. Perennial vegetation has reestablished to reference area levels.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources