







Produced water vessel excavation. No environmental impacts were visible in situ and no groundwater was observed in the open excavation. Orange construction fencing surrounds the excavation.



