

Inspection Photos  
Location Name: ANDERSON #1R (1R)  
Location ID: 306779



Inspection Photos  
Location Name: ANDERSON #1R (1R)  
Location ID: 306779





**Inspection Photos**  
**Location Name: ANDERSON #1R (1R)**  
**Location ID: 306779**



**Inspection Photos**  
**Location Name: ANDERSON #1R (1R)**  
**Location ID: 306779**





**Inspection Photos**  
**Location Name: ANDERSON #1R (1R)**  
**Location ID: 306779**




# Inspection Photos

Location Name: ANDERSON #1R (1R)

Location ID: 306779



May 21, 2025 at 3:4  
9587  
Ignacio C  
Unit



May 21, 2025 at 3:4  
9587  
Ignacio C  
Unit

RED CEDAR GATHERING COMPANY						
Producer:	Hilcorp		Location:	Anderson 1-R		Well ID #: 1540001
Date	N <sub>2</sub>	Methane	CO <sub>2</sub>	Ethane	S.G.	B.T.U.
2/14/24	0.015	95.1	4.61	0.22	0.6017	953.7
5/17/24	0.014	95.1	4.56	0.22	0.6014	954.4
8/29/24	0.016	94.6	5.01	0.26	0.6067	951.4
11/26/24	0.010	95.1	4.66	0.23	0.6021	952.9
2/25/25	0.021	94.8	4.88	0.24	0.6044	957.9



**Inspection Photos**  
**Location Name: ANDERSON #1R (1R)**  
**Location ID: 306779**

