

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
AMATO 11-1 (2025 Seasonal)	Spring	Marco Gonzalez	5/22/2025
Work Summary	Reclamation Type	Land Use	
Innerseeded site	Final Maint	Other	
One-Call Number	Red Zone Rep	Red Zone Date	

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance		No	Location(s): AMATO 11-1 Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: 21,780 sq ft Seed Mix: Sandy Soil 2 (10.00 lbs) Crop Type: Soil Type: Sandy Stabilization Date: Seeding Date: 5/22/2025 Mulch: None Straw Bales: NA Soil Amendment Type: None Soil Amendment Rate: NA Imported Top Soil: NA Top Soil Source: NA General Notes: Job oxrm1011

PHOTOS

Photo Name: Site Map
Description:




Photo Name: Seed Mix
Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:

